

Lieutenant Governor

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA

Division Director

## **Minerals Inspection Report**

Reviewed

08/29/2013 Report Date: Mine Name: Champlin #1 S/023/0104 Mine Status: Active Permit Number: Permit Fees: Delinquent Operator Name: Nephi Sandstone Corporation Inspection Date: 08/14/2013 **Bond Amount:** \$19,700 Inspector(s): Wayne Western Inspection Time: 2:45 - 3:00 pm Attendee(s): Weather: 90's fair sky Bond Escalation: 02/10/2014 Inspection Purpose: Routine inspection Prior Inspection: 04/01/2009 **Conclusions and Recommendations** 

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds		
	The bond is current. Permit fees have not been paid.		
2.	Public Safety (shafts, adits, trash, signs, highwalls)	X Year of December 1	
3.	Protection of Drainages/Erosion Control		
4.	Deleterious Material		
	There are two buckets of hydraulic fluid on the site. The buckets are not in a containment facility and must be stored appropriately.		
5.	Roads (maintenance, surfacing, dust control, safety)		
6.	Reclamation		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
8.	Soils		
9.	Revegetation		
10.	Other		

Inspector's Signature: Wapu Wubter

CC

File: /O/- Inspection Summary/Inspection Forms/Inspection form 3.0.1.pdf




Inspected: 08/14/2013






Pit area

Hydraulic fluid buckets



Pit area, antenna is good landmark for the site



On approach to the site.

